Norwich and Broadland 2016 – 2018 Repeat Flooding (FIR/030R)

The Norwich and Broadland 2016 – 2018 Flood Investigation reported on the internal flooding of eight properties and was published on the Norfolk County Council website. Since publication one of the properties included in the report has been flooded internally a further five times and has provided new evidence of historical flooding. This property was on Chapel Field North, Norwich.

The information below summarises the original flood report and the subsequent reports that have been received since.

FIR30: Chapel Field North

First report (Ref: 3752)

Date	Flood Report	Rainfall within the catchment
23/06/2016	1 property internally flooded.	32mm rainfall was recorded as falling in 2
	Report received from resident via	hours 0 minutes at the Norwich Heigham
	online flood report on 23 rd	rainfall monitoring station. This intensity
	November 2016 (FWF/16/4/3752)	of rainfall for the total duration equates to
		a 1:16 rainfall event.

Subsequent reports

Date	Flood Report	Rainfall within the catchment
07/12/2018	1 property internally flooded.	8.8mm rainfall was recorded as falling in 4
	Report received from resident via	hours 30 minutes at the Norwich Heigham
	email correspondence on 9th	rainfall monitoring station. This intensity of
	January 2019 (FWF/18/1506)	rainfall for the total duration is too small to
		calculate a rainfall intensity.
08/12/2018	1 property internally flooded.	2.4mm rainfall was recorded as falling in 1
	Report received from resident via	hour at the Norwich Heigham rainfall
	email correspondence on 9th	monitoring station. This intensity of rainfall
	January 2019 (FWF/18/1507)	for the total duration is too small to
		calculate a rainfall intensity.
16/12/2018	1 property internally flooded.	1.6mm rainfall was recorded as falling in 3
	Report received from resident via	hours at the Norwich Heigham rainfall
	email correspondence on 9th	monitoring station. This intensity of rainfall
	January 2019 (FWF/18/1508)	for the total duration is too small to
		calculate a rainfall intensity.
21/12/2018-	1 property internally flooded.	12mm rainfall was recorded as falling in 1.3
22/12/2018	Report received from resident via	hours overnight at the Norwich Heigham
	email correspondence on 9th	rainfall monitoring station. This intensity of
	January 2019 (FWF/18/4/7611)	rainfall for the total duration is too small to
		calculate a rainfall intensity.
07/04/2019	1 property internally flooded.	7.8mm rainfall was recorded as falling in 1
	Report received from resident via	hour at the Norwich Heigham rainfall
	the telephone on 11 th June 2019	monitoring station. This intensity of rainfall
	(FWF/19/1509)	for the total duration is too small to
		calculate a rainfall intensity.
11/06/2019	1 property internally flooded.	22.2mm rainfall was recorded as falling in
	Report received from resident via	17 hours 15 minutes at the Norwich
		Heigham rainfall monitoring station. This

the telephone on 11 th June 2019	intensity of rainfall for the total duration is
(FWF/19/1079)	too small to calculate a rainfall intensity.

The Norwich Heigham rainfall gauge was under recording by 5.32% throughout December 2018 and under recording by 6.00% in April 2019. Therefore, rainfall values will be slightly higher than recorded.

Recommendations

The following recommendations were made during the investigation of flooding that occurred on the 23/06/2019.

- Anglian Water should work with partner organisations to identify the potential for managing the amount or rate of surface water entering their drainage system in flood events.
- Property owners should protect their buildings through flood resilience measures where appropriate. NCC will advise them of the appropriate measures they could take to protect their property without prejudicing the rights and responsibilities of adjoining property holders.

Actions being undertaken

 Anglian Water has identified a potential solution to the flooding and is exploring how this could be implemented/funded with the resident.