

Appendix D. Recorded Historical Flood Incidents

D.1. Historical Surface Water Recorded Incidents from the Environment Agency

Date	Town	Source	Comments
			excess surface water run off - highway drainage overwhelmed, groundwater
01/03/1985	Ashwicken	Multiple	flooding.
01/12/1993	Ingoldisthorpe	Pluvial	excess surface water run off, possible groundwater flooding too
01/02/1987	Kings Lynn	Pluvial	Excess surface water run off - drainage system overwhelmed Garden flooded. It is possible that groundwater flooding occurred as a result of high water levels in the Tottenhill gravels. It also may be just poor surface
01/12/2008	Kings Lynn	Multiple	drainage or perhaps a burst water mains pipe.
01/03/2001	Northwold	Pluvial	Excess surface water run off - garage flooded
01/04/2001	Outwell	Sewer	reports of sewers surcharging in roads
01/07/1998	Shouldham	Pluvial	excess surface water run off - drainage system overwhelmed
01/07/1998	Shouldham	Pluvial	excess surface water run off - drainage system overwhelmed
01/04/2003	Shouldham	Multiple	fluvial flooding and high water table reported.

D.2. Historical Recorded Flood Events from Norfolk Fire and Rescue Service

Incident Number	Station	Post Code	Service
018472-26012002	HEA	PE317AD	Water removal/provision
018682-30012002	LYN	PE301QB	Water removal/provision
008045-30072002	LYN	PE305EZ	Water removal/provision
008050-30072002	LYN	PE330PF	Water removal/provision
008083-30072002	LYN	PE302AQ	Water removal/provision
008151-31072002	LYN	PE301AA	Water removal/provision
013450-15102002	LYN	PE343AX	Water removal/provision
017472-22122002	LYN	PE316AA	Water removal/provision
017847-30122002	LYN	PE316AB	Water removal/provision
017856-30122002	SAN	PE316BZ	Water removal/provision
018564-13012003	OUT	PE148ES	Water removal/provision
018816-19012003	WWA	PE147NP	Water removal/provision
021788-20032003	LYN	PE302LE	Water removal/provision
005004-17062003	DMK	PE389AW	Water removal/provision
020245-31012004	WWA	PE147HA	Water removal/provision
022002-07032004	HUN	PE366EB	Water removal/provision
003026-26052004	LYN	PE301NN	Water removal/provision
005877-08072004	DMK	PE389DJ	Water removal/provision
005879-08072004	DMK	PE389JE	Water removal/provision
005880-08072004	DMK	PE389JR	Water removal/provision
005882-08072004	DMK	PE389EE	Water removal/provision
005884-08072004	DMK	PE389DL	Water removal/provision
005886-08072004	DMK	PE389EW	Water removal/provision
008089-13082004	HUN	PE318DD	Water removal/provision
009083-31082004	LYN	PE304SW	Water removal/provision
010346-20092004	LYN	PE305LB	Water removal/provision
011738-15102004	DMK	PE380EP	Water removal/provision
008938-31082005	HUN	PE365AR	Water removal/provision
009530-09092005	MET	IP264PS	Water removal/provision
011824-19102005	LYN	PE344DT	Water removal/provision
012627-02112005	MET	IP264PR	Water removal/provision
013020-08112005	MET	IP264PE	Water removal/provision
013085-09112005	LYN	PE304SH	Water removal/provision
020177-20032006	LYN	PE304XG	Water removal/provision
009591-26072006	MET	IP264AD	Water removal/provision
011640-17082006	DMK	PE339BA	Water removal/provision
011905-21082006	DMK	PE389SY	Water removal/provision
014120-22092006	DMK	PE389EW	Water removal/provision
018358-22112006	LYN	PE302NX	Water removal/provision